

R177-162-65 9

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$10.00

TYPE BUILDINGS

| | | | | |
|----------------------|----------|-------------------------------------|-----------------|---------------|
| PERMIT NO. S-4323 | LOCATION | 2900 - Florin Road | | A-5 |
| DATE Sept 2-65 | PURPOSE | Const. sign Class N | | |
| ZONE C-2 | OWNER | Shell Oil Co. same | | |
| | ARCH'T | | | |
| | CONTR | Pacific Neon 909-Fee Drive WA7-0527 | | |
| VAL. \$900. | STORIES | ROOMS | APTS. | SIZE |
| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | PHONE (O) (C) |
| FORM | | | | |
| JOIST | | | | |
| FRAME | | | | |
| SHEET | | | | |
| ROCK | | | | |
| FINAL | 11-25-65 | P. H. L. | | ent. |

10-4-65 11:07 up. out in 1/R 10-25-65 Dickla

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|--------------------|--------------------------------------|
| 10-4-65 | 11:07 up. out in 1/R 10-25-65 Dickla |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| COMPLETE AND OK | INSPECTOR |