

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS 19-Glenville Circle					INSPECTION AREA 1	FINAL INSPECTIONS	
LEGAL DESCRIPTION Lot 1027 Glenbrook #10		OCCUP. GR.	CONST TYPE	VAR. NO.	FIRE ZONE	BUILDING BY Barbato		DATE 10/2/68	
TITLE AND NAME Besco		1/C	ADDRESS San Leandro, Cal.	ZIP	CITY LIC. NO.	TEL. NO.	ELECTRICAL BY	DATE	
GEN. CONTR.	Same						PLUMBING BY	DATE	
ELEC. CONTR.							MECHANICAL BY	DATE	
PLBG. CONTR.							CERTIFICATE OF OCCUPANCY		
MECH. CONTR.							ISSUED BY	DATE	
ARCH. ENGR.									
OWNER	Barbrook, Inc.		2777-Alvarado St. LS						
CONST. LOAN LENDER									
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR	TOTAL AREA	C.S.D.	C.I. CASE	
					460-garage	1,525 sq. ft.			
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	EXISTING BLDG'S SAME LOT	HOW USED	

NATURE OF WORK:- **Const. dwelling & attached garage Plan 101**

PERMIT NO. S.P. - G-715		MICROFILM RECORD			
ISSUED BY					
ISSUANCE DATE 6/19/68	PLANS AND APPLICATION	REEL NO. 240	FRAME NO:- 389	TO	
VALUATION \$ 15,100.00	INSPECTION RECORD	REEL NO. 229	FRAME NO:- 71	TO	80
R.D.F. FEE \$	JOB FILE	REEL NO.	FRAME NO:-	TO	
S.M.I. FEE \$					
PLAN CK. FEE \$					
SEWER INCL. FEE \$					
PERMIT FEE \$ 55.00	REMARKS AND/OR VARIANCES				
\$	DWELLING				
\$					
TOTAL FEES \$					

23077280 - final

