

R-277 F 224

Lot 1082		BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD			\$80.00
Glenbrook #10		TYPE BUILDINGS		R-180 F-276-287 - Plumb R-195 F-309-313 - Elevation R-197 F-553 - Ceiling Joint	
PERMIT NO.					
G-5937	LOCATION 23 - Moss Glen Circle A-1 (52)				
DATE	PURPOSE Const. dwelling & att. gar. MP# 403				
3-10-70	OWNER Valbrook, Inc. 2777-Alvarado St. S.L.				
ZONE	ARCH'T				
R-1	CONTR Besco Bldrs. same		San Leandro		
VAL. \$21,300.		STORIES	ROOMS	APTS.	500-gar. SIZE 1,394-sq.ft.
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP		PHONE (O) (C) 483-4300
FORM	3-16-70	Miller			
JOIST	4-9-70	Miller			
FRAME	5-15-70	Miller			
SHEET NOCK	5-26-70	Miller			
FINAL	11-29-70	Mr Calloway			

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
4-23-70	OK slab <span style="float: right;">Crews</span>
10-22-70	OK final - Sealed <span style="float: right;">C. Williams</span>
COMPLETE AND OK	INSPECTOR