

R-277 F 224

Lot 1082		BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD			\$80.00
Glenbrook #10		TYPE BUILDINGS			R-180 F-276-287-Plumb R-195 F-309-313-Elevation R-197 F-553-Ceiling Joint
PERMIT NO. G-5937	LOCATION 23 - Moss Glen Circle A-1 (52)				
DATE 3-10-70	PURPOSE Const. dwelling & att. gar. MP# 403				
ZONE R-1	OWNER Valbrook, Inc. 2777-Alvarado St. S.L.				
	ARCH'T	CONTR Besco Bldrs. same San Leandro			
VAL. \$21,300.	STORIES	ROOMS	APTS.	500-gar.	SIZE 1,394-sq.ft.
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C) 483-4300	
FORM	3-16-70	Miller			
JOIST	4-9-70	Miller			
FRAME	5-15-70	Miller			
SHEET NOCK	5-26-70	Miller			
FINAL	11-29-70	Mr Callaway			

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
4-23-70	OK slab Crews
10-22-70	OK final - Sealed C. Williams
COMPLETE AND OK	INSPECTOR