

RECORD OF SUBSEQUENT PERMITS ISSUED

DATE	TYPE OF PERMIT AND VALUATION	PERMIT NO. AND FEE	NATURE OF WORK	PRESENT OWNER AND ADDRESS	CONTRACTOR & ADDRESS	FINALED BY	DATE
1/19/77	P. E. \$ 1000	E-384 \$ 30.00 <i>G-9078</i>	Correct Plumbing Viol # 2052 -C & Elect Viol # 162 Auto Body Repair	Jose Ruiz 34661 Attawa Ave.	Owner Same	<i>Clark</i> <i>Diloreto</i>	<i>4/27/77</i> <i>8/26/77</i>
6-7-77	E \$200	E-4006 \$20 <i>G-9915</i>	elec. sign	Foster & Kleiser POB 71, Sac	Collins Elec. POB 507, Sac	<i>Clark</i>	<i>6/13/77</i>
9-2-77	Elec. \$50.00	E-6987 \$7.50 <i>C-7569</i>	Replace branch cir- cuit wiring to sign damaged by fire to	Foster & Klaiser P. O. Box 71	Collins Elec. P. O. Box 507	<i>Clark</i>	<i>9-7-77</i>
11/28/77	P. \$100	E-9623 \$20.	Cap sewer Line comm Bldg.	Joe Ruiz	Owner	<i>Galloway</i>	<i>12/16/77</i>
11/28/77	Wreck	W-7415 \$Gratis	Wreck-Gar	Jose Ruiz	Owner	<i>Galloway</i>	<i>12/16/77</i>

MICROFILM RECORD

PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.
E-384	<i>R470F327</i>	E-9623	R-503F069		
E-4006	<i>R484F071</i>	W-7415	R-503F069		
<i>E-4006</i>	<i>R-501-F-495</i>	E-9623	R-505F571 - Final		
E-6987	R-493 F-439	W-7415	R-505F571 - Final		
E-6987	<i>R501F495</i>				
<i>C-364</i>	<i>R501F495</i>				

