

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS				INSPECTION AREA		FINAL INSPECTIONS		
		2756 Bridgeford Drive				A-6				
LEGAL DESCRIPTION					OCCUP. GR.	CONST TYPE	VAR. NO.	FIRE ZONE	BUILDING BY	DATE
Northgate Unit #9 Lot 1173									Riolo	9-4-70
TITLE AND NAME		1/C	ADDRESS		ZIP	CITY LIC. NO.	TEL. NO.		ELECTRICAL BY	DATE
GEN. CONTR. Owner										
ELEC. CONTR.									PLUMBING BY	DATE
PLBG. CONTR.										
MECH. CONTR.									MECHANICAL BY	DATE
ARCH. ENGR.										
OWNER Taylor-Mazza, Inc.									CERTIFICATE OF OCCUPANCY	
CONST. LOAN LENDER									ISSUED BY	DATE
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR	504 Car. AREA	C.S.D.	C.I. CASE		
						1200 sq ft	CENSUS TRCT. NO.			
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	EXISTING BLDG'S SAME LOT	HOW USED		
			R-1							

NATURE OF WORK:- Const. dwelling and garage MP #3-3

PERMIT NO. S.P. - G-6790		MICROFILM RECORD			
ISSUED BY		PLANS AND APPLICATION		REEL NO. 281	FRAME NO.: 218 TO
ISSUANCE DATE	May 13-70	INSPECTION RECORD		REEL NO. 411	FRAME NO.: 600 - combine
VALUATION	\$ 18,400	JOB FILE		REEL NO.	FRAME NO.: TO
R.D.F. FEE	\$				
S.M.I. FEE	\$				
PLAN CK. FEE	\$				
SEWER INCL. FEE	\$				
PERMIT FEE	\$	REMARKS AND/OR VARIANCES			
	\$	Form: 6-11-70 Calloway			
	\$	Frame: 7-29-70 Riolo			
TOTAL FEES	\$ 71	Sheet Rock: 8-5-70 Riolo			

