

B154 7381-385

| | | | | |
|--------------------------|-----------------|--|---|----------------------------|
| E ³ of Lot 20 | | BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD | | \$61.00 |
| Blk. 33, West | | TYPE BUILDINGS | | <i>R246 F-206 (Nettec)</i> |
| Del Paso Heights. | | | | <i>B156 7378</i> |
| PERMIT NO. | E-8622 | LOCATION | 620 - South Street <i>AVENUE</i> | <i>A-7</i> A-6 |
| DATE | Oct 7-64 | PURPOSE | Const. Church with attached dwelling | |
| ZONE | R-1 | OWNER | Harvey J. Phillips 616 - South St. | |
| | | ARCH'T | | |
| | | CONTR | Gauranteed Homes 4201-Manzanita Av. | |
| VAL. | \$17,600. | STORIES | 1 | ROOMS |
| | | | | APTS. |
| | | | | SIZE |
| | | | | 2,280 sq. ft. |
| INSP. | DATE | BLDG. TYPE | VENÖ hr. | OCCUPANCY GROUP |
| | | | | B-3 |
| FORM | <i>10-16-64</i> | <i>McCallum</i> | | |
| JOIST | | | | |
| FRAME | <i>11-16-64</i> | <i>J. Phillips</i> | | |
| SHEET ROCK | <i>11-25-64</i> | <i>Dana Fuller</i> | | |
| FINAL | <i>2-18-65</i> | <i>Chopin</i> | | |

not done



| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|--------------------|--|
| 10-28-64 | OK O.K. Wall Nail Mr. Calloway |
| 10-28-64 | OK Roof Nail Mr. Calloway |
| 11-9-64 | Footings undermined, sketches required to submit corrections J. Barbato |
| 11-23-64 | 1st. fire Wall incorrect J. Barbato 1st. occupancy separation, incorrect J. Barbato |
| 2-11-65 | Fencing - P.T. NOT PARKING DESIGNATED - E. Quinn |
| 2-16-65 | P.T. NOT ENOUGH PARKING - O.K. BLAG TO BE DEMO. E. Quinn |
| | |
| | |
| | |
| COMPLETE AND OK | INSPECTOR |

