

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

| | |
|-----------------------------|--|
| PERMIT NO. <i>B-3753</i> | LOCATION <i>2309 - Tortola Way.</i> |
| DATE <i>Apr. 13-57</i> | PURPOSE <i>Repairs to garage</i> |
| ZONE | OWNER <i>U. O. Black</i> |
| | ARCH'T. |
| | CONTR. <i>Owner</i> |

| | | | | |
|------------------------------|---------|-------|-------|------|
| VAL. <i>150⁰⁰</i> | STORIES | ROOMS | APTS. | SIZE |
|------------------------------|---------|-------|-------|------|

| | | | |
|-------------------|--|------------------|--|
| LIGHT SHAFTS | | ELEVATOR SHAFTS | |
| VENT SHAFTS | | BOILER ROOMS | |
| OWNER'S INSPECTOR | | SPRINKLER SYSTEM | |
| LATH | | GAS VENTS | |
| FIRE ESCAPES | | CHIMNEYS | |
| STAND PIPES | | SKYLIGHTS | |

..DATE.

CONDITION OF WORK—REMARKS

**COMPLETE
AND O. K.**

INSPECTOR