

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-33223</i>	LOCATION <i>1318-4th street</i>
DATE <i>3-26-51</i>	PURPOSE <i>Repair roof.</i>
ZONE	OWNER <i>Shikashige</i>
	ARCH'T.
	CONTR. <i>H. Yonessaki</i>

VAL. <i>\$ 200</i>	STORIES	ROOMS	APTS.	SIZE
--------------------	---------	-------	-------	------

LIGHT SHAFTS	ELEVATOR SHAFTS
VENT SHAFTS	BOILER ROOMS
OWNER'S INSPECTOR	SPRINKLER SYSTEM
LATH	GAS VENTS
FIRE ESCAPES	CHIMNEYS
STAND PIPES	SKYLIGHTS

DATE	CONDITION OF WORK—REMARKS
COMPLETE AND O. K.	INSPECTOR