

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-10,849</i>	LOCATION <i>590 - Pala Way.</i>
DATE <i>11/12/42</i>	PURPOSE <i>General repairs to dwg.</i>
ZONE	OWNER <i>John Laddick</i>
	ARCH'T.
	CONTR. <i>Owner</i>

VAL. <i>15000</i>	STORIES	ROOMS	APTS.	SIZE
-------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
	<p data-bbox="304 930 446 969">COMPLETE AND O. K.</p> <p data-bbox="1253 947 1404 969">INSPECTOR</p>