

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-11451</i>	LOCATION <i>102 2 1/2 - 2nd St.</i>
DATE <i>7/30/43</i>	PURPOSE <i>Repairs to interior</i>
ZONE	OWNER <i>Union Hotel.</i>
	ARCH'T.
	CONTR. <i>Quone</i>

VAL. <i>190⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS			ELEVATOR SHAFTS	
VENT SHAFTS			BOILER ROOMS	
OWNER'S INSPECTOR			SPRINKLER SYSTEM	
LATH			GAS VENTS	
FIRE ESCAPES			CHIMNEYS	
STAND PIPES			SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
COMPLETE AND O. K.	INSPECTOR