

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>H-4153</i>	LOCATION <i>81 - Gas Alley.</i>			
DATE <i>4/8/36</i>	PURPOSE <i>Repairs to floor ducts</i>			
ZONE <i>1000 sq</i>	OWNER <i>Frank Busick</i>			
ARCH'T. <i>Owner</i>	CONT'R. <i>Owner</i>			
VAL. <i>7000</i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS	<i>See other side</i>		ELEVATOR SHAFTS	
VENT SHAFTS			BOILER ROOMS	
OWNER'S INSPECTOR			SPRINKLER SYSTEM	
LATH			GAS VENTS	
FIRE ESCAPES			CHIMNEYS	
STAND PIPES			SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
4/22/36	1 ST / NSP. Forms for New Concrete Foundation & concrete walk at edge of 2 nd Story Frame ^{OK} OK Completed
5/14/36	2 ND / NSP. Frame for " . Raised valuation from 250 ⁰⁰ to 1000 ⁰⁰ as Owner did considerable additional work on 2 nd Story than originally intended. Now O.K. OK Completed
5/14/36	Issued Additional Permit for work to be done
	<p data-bbox="319 837 450 878">COMPLETE AND O. K.</p> <p data-bbox="1150 857 1282 878">INSPECTOR</p>