

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>H-4153</i>	LOCATION <i>81 - Gas Alley.</i>				
DATE <i>4/8/36</i>	PURPOSE <i>Repairs to floor ducts</i>				
ZONE <i>1000 sq</i>	OWNER <i>Frank Busick</i>				
ARCH'T. <i>Owner</i>	CONT'R. <i>Owner</i>				
VAL. <del><i>7000</i></del>	STORIES	ROOMS	APTS.	SIZE	
LIGHT SHAFTS	<i>See other side</i>		ELEVATOR SHAFTS		
VENT SHAFTS			BOILER ROOMS		
OWNER'S INSPECTOR			SPRINKLER SYSTEM		
LATH			GAS VENTS		
FIRE ESCAPES			CHIMNEYS		
STAND PIPES			SKYLIGHTS		

DATE	CONDITION OF WORK—REMARKS
4/22/36	1 <sup>ST</sup> / NSP. Forms for New Concrete Foundation & concrete walk at edge of 2 <sup>nd</sup> Story Frame <sup>OK</sup> <del>OK</del> <del>Completed</del>
5/14/36	2 <sup>ND</sup> / NSP. Frame for " . Raised valuation from \$450 <sup>00</sup> to 1000 <sup>00</sup> as Owner did considerable additional work on 2 <sup>nd</sup> Story than originally intended. Now O.K. <del>OK</del> <del>Completed</del>
5/14/36	Issued Additional Permit for work to be done
	<p style="text-align: center;">COMPLETE AND O. K.</p> <p style="text-align: right;">INSPECTOR</p>