

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS				INSPECTION AREA	FINAL INSPECTIONS		
		70 Ardsley Circle				A-5			
LEGAL DESCRIPTION				OCCUP. GR.	CONST TYPE	VAR. NO.	FIRE ZONE	BUILDING BY	DATE
lot 551 Southgate Meadows								Riolo	4-11-69
TITLE AND NAME		1/C	ADDRESS		ZIP	CITY LIC. NO.	TEL. NO.	ELECTRICAL BY	DATE
GEN. CONTR. Besco			same						
ELEC. CONTR.								PLUMBING BY	DATE
PLBG. CONTR.									
MECH. CONTR.								MECHANICAL BY	DATE
ARCH. ENGR.									
OWNER Valbrook, Inc.			2777 Alvarado St. San Leandro, Calif				CERTIFICATE OF OCCUPANCY		
CONST. LOAN LENDER							ISSUED BY		DATE
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR	TOTAL AREA	C.S.D.	C.I. CASE	
			1			462 gar			
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	CENSUS TRCT. NO.	EXISTING BLDG'S SAME LOT	HOW USED
			R-1			1525 sq ft			

NATURE OF WORK:- Const dwelling and att gar Plan 101s

PERMIT NO. S.P. -	G-1795	MICROFILM RECORD				
ISSUED BY		PLANS AND APPLICATION	REEL NO.	FRAME NO.:-		
ISSUANCE DATE	10-24-68	INSPECTION RECORD	REEL NO. R413T464	71	TO 80	
VALUATION	\$ 15,100	JOB FILE	REEL NO.	FRAME NO.:-	TO 405	
R.D.F. FEE	\$					
S.M.I. FEE	\$					
PLAN CK. FEE	\$					
SEWER INCL. FEE	\$					
PERMIT FEE	\$ 55.00	REMARKS AND/OR VARIANCES				
	\$	form 12-2-68 Calloway				
	\$	joist 12-20-68 Calloway				
TOTAL FEES	\$	frame 3-4-69 Riolo				
		sht rk 3-7-69 Riolo				

