



RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS		INSPECTION AREA	
15 Dalby Court		5			
LEGAL DESCRIPTION					
Lot 333 Southgate Meadows #5					
TITLE AND NAME		ADDRESS		ZIP	
Valbrook, Inc.		2777-Alvarado St. San Leandro		94608	
CONST. LOAN LENDER					
GEN. CONTR. Besco					
ELEC. CONTR.					
PLBG. CONTR.					
MECH. CONTR.					
ARCH. ENGR.					
OWNER					
CENSUS TRCT. NO.		C.S.D.		C.I. CASE	
130054-15					
BLDG. WIDTH		BLDG. LENGTH		TOTAL HEIGHT	
SIDE YARDS		REAR YARDS		SET BACK REQ.	
NATURE OF WORK:-		Const. dwlg. & att. gar. Plan 502 1B			

PERMIT NO. S.P. - F-3223		ISSUED BY:	
MICROFILM RECORD			
ISSUANCE DATE		2/24/66	
VALUATION		\$12,900.00	
R.O.P. FEE		\$	
JOB FILE		REEL NO. 153	
INSPECTION RECORD		FRAME NO. 492-497	
FRAME NO. TO		580	
FRAME NO. TO		497	
S.M.I. FEE		\$	
PLAN CK. FEE		\$	
SEWER INCL. FEE		\$	
PERMIT FEE		\$46.00	
TOTAL FEES		\$	

REMARKS AND/OR VARIANCES	
DWELLING	
R593R530 - Final	