

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS					INSPECTION AREA		FINAL INSPECTIONS	
		5416 Carmen Way					4			
LEGAL DESCRIPTION					OCCUP. GR.	CONST TYPE	VAR. NO.	FIRE ZONE	BUILDING BY	DATE
TITLE AND NAME		1/C	ADDRESS		ZIP	CITY LIC. NO.	TEL. NO.		ELECTRICAL BY	DATE
GEN. CONTR.										
ELEC. CONTR.									PLUMBING BY	DATE
PLBG. CONTR.										
MECH. CONTR.									MECHANICAL BY	DATE
ARCH. ENGR.										
OWNER									CERTIFICATE OF OCCUPANCY	
CONST. LOAN LENDER									ISSUED BY	DATE
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR	TOTAL AREA	C.S.D.	C.I. CASE		
						CENSUS TRCT. NO.				
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	EXISTING BLDG'S SAME LOT	HOW USED		

NATURE OF WORK:-

PERMIT NO. S.P. -		MICROFILM RECORD			
ISSUED BY					
ISSUANCE DATE	PLANS AND APPLICATION				
VALUATION	\$	INSPECTION RECORD	REEL NO.	FRAME NO:-	TO
R.D.F. FEE	\$	JOB FILE	REEL NO.	FRAME NO:-	TO
S.M.I. FEE	\$				
PLAN CK. FEE	\$				
SEWER INCL. FEE	\$				
PERMIT FEE	\$	REMARKS AND/OR VARIANCES			
	\$				
	\$				
TOTAL FEES	\$				

5416 Carmen Way
A-4
RECORD OF SUBSEQUENT PERMITS ISSUED

DATE	TYPE OF PERMIT AND VALUATION	PERMIT NO. AND FEE	NATURE OF WORK	PRESENT OWNER AND ADDRESS	CONTRACTOR & ADDRESS	FINALED BY	DATE
7/22/63	B. \$500.	E-4497 \$5.00	Const. Aluminum patio on Dwig.	Henry Lau	Air-Kool Alum. 2920 Arden Way	Hammons	8/13/63
3/23/76	B. \$700.	D-1919 \$15.	Pest Repair - Dwig.	Do Lau	Orchard Supply Co.	R. Luo	4-15-76

MICROFILM RECORD

PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.
E-4497	R 126 F. 118				
D-1919	R 439R 310 R 439R 310 R 439R 310 R 439R 310 R 439R 310 R 439R 310				
D1919	528				