

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE VII BUILDINGS

PERMIT NO.

1391

LOCATION

324 f Stone Archway

PURPOSE

Por Garage attached

ROOMS

APTS.

DATE

35 FEB 1927

OWNER

W. J. Furber

PHONE

ARCH'T

A. J. Calder

OCT 5 1927
SACRAMENTO BUILDING DIVISION

CONT'R

VAL.

245

STORIES

SIZE

| FOUNDATION | STORY | BSMT | 1 | 2 | 3 | ROOF | | |
|------------|-------------------------|------|---|---|---|------|------------------|---------------|
| Ex Wall | Jolts | | | | | | Chimneys | Cement Tests |
| | Beams and Girders | | | | | | Fire Place | |
| Int Wall | Studs and Columns | | | | | | Gas Water Heater | Window Courts |
| | Bridging Fire Stops | | | | | | Heater Closet | |
| Piers | Fire Escape Stand Pipes | | | | | | Furnace | |
| | Metal Lath | | | | | | Boiler Room | |
| | Stairs | | | | | | Elevator Shaft | |

| DATE | CONDITION OF WORK—REMARKS |
|------|---|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | <p data-bbox="329 828 476 875">COMPLETED AND O. K.</p> <p data-bbox="1176 854 1312 875">INSPECTOR</p> |