

R-113 E 327

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$5.00**

**TYPE BUILDINGS**

<b>PERMIT NO.</b> R-2970		<b>LOCATION</b> 2314 - V Street		<b>A-2</b>	
<b>DATE</b> Jan. 3-63		<b>PURPOSE</b> Const. carport on rear of property.			
<b>ZONE</b> R-1		<b>OWNER</b> Tashimetsu Nagae		<b>Same</b>	
		<b>ARCH'T</b>			
		<b>CONT'R</b> Owner		<b>GL 6-4002</b>	
<b>VAL.</b> \$400.		<b>STORIES</b>	<b>ROOMS</b>	<b>APTS.</b>	<b>SIZE</b> 264 sq. ft.
<b>INSP.</b>	<b>DATE</b>	<b>BLDG. TYPE</b>		<b>OCCUPANCY GROUP</b>	
<b>FORM</b>					
<b>JOIST</b>					
<b>FRAME</b>	1-16-63	McCalloway			
<b>SHEET ROCK</b>					
<b>FINAL</b>	1-16-63	McCalloway			
					MC

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
	<b>COMPLETE AND OK</b>

**INSPECTOR**