

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>#-7909</i> DATE <i>3/2/37</i> ZONE	LOCATION	<i>2504-V St.</i>
	PURPOSE	<i>Repairs to roof due to storm.</i>
	OWNER	<i>F. Clark</i>
	ARCH'T.	
	CONTR.	<i>Owner</i>

VAL. <i>17000</i>	STORIES	ROOMS	APTS.	SIZE
-------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
	COMPLETE AND O. K.

INSPECTOR