

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-3759</i>	LOCATION <i>609 - PRT.</i>			
DATE <i>1/4/36</i>	PURPOSE <i>Repair two Jam dwell peritor</i>			
ZONE	OWNER <i>F. Pukermacher</i>			
	ARCH'T.			
	CONT'R. <i>Chas L. Vanina 2022-M.</i>			
VAL. <i>1000⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
1/2/55	2 ND WSP. P... AW... <i>[Handwritten signature]</i>
1/2/55	2 ND WSP. P... <i>[Handwritten signature]</i>
2/2/55	3 RD WSP. P... <i>[Handwritten signature]</i>
	4 TH WSP. Repairs to 2 ND St. City Council % Fire Dept. O.K. AW <i>[Handwritten signature]</i>
	<i>[Large diagonal slash across the page]</i>
2/2/55	COMPLETE AND O. K. <i>[Handwritten signature]</i> INSPECTOR