

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD \$8.50

**TYPE BUILDINGS**

*P. 85 7528*

<b>PERMIT NO.</b> D-8927	<b>LOCATION</b> 823 - Q Street	A-2
<b>DATE</b> Jun 26-61	<b>PURPOSE</b> Repair fire damage to dwelling.	
<b>ZONE</b>	<b>OWNER</b> G. F. Bertaina	Same
	<b>ARCH'T</b>	IV 9-8032
	<b>CONT'R</b> T. F. Merrill & Co. 2524 - Tesla	

<b>VAL.</b> \$1,850.	<b>STORIES</b>	<b>ROOMS</b>	<b>APTS.</b>	<b>SIZE</b>
----------------------	----------------	--------------	--------------	-------------

<b>INSP.</b>	<b>DATE</b>	<b>INSPECTOR</b>
<b>FORM</b>		
<b>JOIST</b>		
<b>FRAME</b>	<i>6-27-61 Jones</i>	
<b>LATH</b>		
<b>FINAL</b>	<i>10-20-61 Fuller</i>	

<b>DATE</b>	<b>SPECIAL CONDITIONS OF WORK—REMARKS</b>
	<b>COMPLETE AND OK</b> <span style="float: right;"><b>INSPECTOR</b></span>