

**BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD**

**TYPE VII BUILDINGS**

<b>PERMIT NO.</b> 59 N	<b>LOCATION</b> 177 5th Ave 22 27 28			<b>2701 0 St</b>		
<b>DATE</b> 2/21/31	<b>PURPOSE</b> F 12 V Reg. Garage	<b>ROOMS</b> 6	<b>APTS.</b>			
<b>ZONE</b>	<b>OWNER</b> Ray & Armstrong 2705			<b>PHONE</b>		
	<b>ARCH'T</b> A E Erickson					
	<b>CONT'R</b> A E Erickson					
	<b>VAL.</b> 4570 -	<b>STORIES</b> 1	<b>SIZE</b> 34 x 46 - 20			

FOUNDATION	STORY	BSMT	1	2	3	ROOF			
EX WALL	Joints						Furnace	8 x 12	Cement Tests
	Beams and Girders						Chimneys	8 x 12	
Int Wall	Studs and Columns						Fireplace		
	Bridging Fire Stops						Fire Place		
Piers	Fire Escape Stand Pipes						Gas Water Heater		
	Metal Lath						Heater Closet		
	Stairs						Furnace		Window Courts
							Boiler Room		
							Elevator Shaft		

DATE	CONDITION OF WORK—REMARKS
3/5/30	1 <sup>st</sup> Insp. Form in place <sup>including 8' basement walls</sup> OK A.W. Campbell
4/3/30	2 <sup>nd</sup> Insp. Frame " " A.W. Campbell
4/15/30	3 <sup>rd</sup> " Int. Lush OK + in place R.H. Rutter
5/23-30	4 <sup>th</sup> " Insp. Final OK Certificate of occupancy issued.
	Street cleaned up
	and OK
	<div style="display: flex; justify-content: space-between;"> <span data-bbox="314 866 474 909">COMPLETED AND O.K.</span> <span data-bbox="541 809 1044 932">R.H. Rutter</span> <span data-bbox="1165 888 1312 909">INSPECTOR</span> </div>