

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-7592</i>	LOCATION <i>1214 - P. Street.</i>
DATE <i>3/3/41</i>	PURPOSE <i>Make addn. to rear bldg.</i>
ZONE <i>MULTI-FAM</i>	OWNER <i>Dr. W. Suck.</i>
	ARCH'T.
	CONTR. <i>R. H. Rutter</i>

VAL. <i>7000.00</i>	STORIES <i>—</i>	ROOMS <i>8</i>	APTS.	SIZE
---------------------	---------------------	-------------------	-------	------

LIGHT SHAFTS	<i>Note: Windows not</i>	ELEVATOR SHAFTS	<i>Area</i>
VENT SHAFTS	<i>were not</i>	BOILER ROOMS	
OWNER'S INSPECTOR	<i>on front of bldg.</i>	SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
3/24/41	1 ST /NSP - Forms in place ^{OK} A.W. Campbell
4/25/41	2 ND /NSP. Part Frame ^{OK} A.W. Campbell
5/2/41	2 ND /NSP. Bal. of Frame ^{OK} A.W. Campbell
5/21/41	3 RD /NSP. INT. LATA (Front Part) A.W. Campbell.
8/15/41	4 TH /NSP. Body Completed OK
8/15/41	COMPLETE AND O. K. <i>Alfred W. Campbell</i> INSPECTOR