

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS					INSPECTION AREA	FINAL INSPECTIONS		
LEGAL DESCRIPTION					OCCUP. GR.	CONST TYPE	VAR. NO.	FIRE ZONE	BUILDING BY	DATE
TITLE AND NAME		1/C	ADDRESS		ZIP	CITY LIC. NO.	TEL. NO.		ELECTRICAL BY	DATE
GEN. CONTR.									PLUMBING BY	DATE
ELEC. CONTR.									MECHANICAL BY	DATE
PLBG. CONTR.										
MECH. CONTR.										
ARCH. ENGR.										
OWNER									CERTIFICATE OF OCCUPANCY	
CONST. LOAN LENDER									ISSUED BY	DATE
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR	TOTAL AREA	C.S.D.	C.I. CASE		
							CENSUS TRCT. NO.			
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	EXISTING BLDG'S SAME LOT	HOW USED		

NATURE OF WORK:

B E P M

PERMIT NO. S.P.	MICROFILM RECORD			
ISSUED BY	PLANS AND APPLICATION	REEL NO.	FRAME NO:-	TO
ISSUANCE DATE	INSPECTION RECORD	REEL NO.	FRAME NO:-	TO
VALUATION \$	JOB FILE	REEL NO.	FRAME NO:-	TO
R.D.F. FEE \$				
S.M.I. FEE \$				
PLAN CK. FEE \$				
SEWER INCL. FEE \$				
PERMIT FEE \$	REMARKS AND/OR VARIANCES			
\$				
\$				
TOTAL FEES \$				

RECORD OF SUBSEQUENT PERMITS ISSUED

DATE	TYPE OF PERMIT AND VALUATION	PERMIT NO. AND FEE	NATURE OF WORK	PRESENT OWNER AND ADDRESS	CONTRACTOR & ADDRESS	FINALED BY	DATE
10-1-79	Elec. \$50.00	G-9910 \$7.50	Replace defective main breaker (had to pull meter to make the change	Robert McKelvey 2571 El Vita 95608	Ballast Man 4141 Tresler Ave 95660	<i>Ballast</i>	10/15/79
			-job was done on Saturday 9-15-79) - Note: this is the separate cottage at that address - not one of the apartments.				

MICROFILM RECORD

PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.
G-9910	R 593 F 2 47				
G-9910	R 595 F 2 06				

found