

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. B-580	LOCATION 4617 Q ST			
DATE MAY 10, 1938	PURPOSE Make Repairs to Damaged Termite Damaged			
ZONE 2-Family	OWNER ANTONIO STEYEN'S 90 S J SMITH 4617 Q ST			
	ARCH'T.			
	CONTR. FIRE & PEST CONTROL LAB. 1119-24 #5			
VAL. 176⁰⁰	STORIES	ROOMS	APTS.	SIZE

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	



DATE	CONDITION OF WORK—REMARKS
	COMPLETE AND O. K. INSPECTOR