

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-12187</i>	LOCATION <i>5308 - S. St.</i>
DATE <i>4/10/44</i>	PURPOSE <i>Re-roof comp. shingles damaged</i>
ZONE	OWNER <i>G. E. Mitchell</i>
	ARCH'T.
	CONTR. <i>Owner</i>

VAL. <i>240⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE
------------------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE.	CONDITION OF WORK—REMARKS
	<p data-bbox="319 868 452 906">COMPLETE AND O. K.</p> <p data-bbox="1219 882 1362 906">INSPECTOR</p>