

R 2410 E 1034

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD

\$Gratis

TYPE BUILDINGS

7367 7139 etc.

| | |
|----------------------|--|
| PERMIT NO. W-4106 | LOCATION 1054 - El Camino Avenue, Rear A-6 |
| DATE Sept-18-68 | PURPOSE Wreck 1-family dwelling |
| OWNER Carl Johnson | Same |
| ZONE | ARCH'T No phone |
| | CONT'R Owner Same |

(69)

| VAL. | STORIES | ROOMS | APTS. | SIZE |
|------------------|-------------------------------------|------------|-----------------|---------------|
| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | PHONE (O) (C) |
| FORM | | | | |
| JOIST | <i>Condensed by Bldg Department</i> | | | |
| FRAME SHEET ROCK | | | | |
| FINAL | <i>11-23-68 P. C. Hammond</i> | | | <i>ELL</i> |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|--------------------|---|
| 10/18/68 | Almost done D-7 11-1-68 Summer |
| 1/1/68 | Foundations almost ^{with} removed |
| | Work Working D-7 11-23-68 Summer |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| COMPLETE AND OK | INSPECTOR |