

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

| | |
|----------------------------|---|
| PERMIT No. <i>T 424</i> | LOCATION <p align="right"><i>2216 P St</i></p> |
| DATE <i>3/8/33</i> | PURPOSE <i>Change Lower to 2 flats</i> |
| ZONE <i>Multi</i> | OWNER <i>John Bagnoni</i> |
| | ARCH'T |
| | CONT-R <i>Owner</i> |

| | | | | | |
|------|--------------|---------|-------|-------|------|
| VAL. | <i>501 -</i> | STORIES | ROOMS | APTS. | SIZE |
|------|--------------|---------|-------|-------|------|

| | | | |
|--------------------------|--|-------------------------|--|
| Light Shafts | | Elevator Shafts | |
| Vent Shafts | | Boiler Rooms | |
| Owner's Inspector | | Sprinkler System | |
| Lath | | Gas Vents | |
| Fire Escapes | | Chimneys | |
| Stand Pipes | | Skylights | |

| DATE | CONDITION OF WORK-REMARKS |
|---------|--|
| 3/21/33 | 2 nd / N.S.P. Frame for remodeling lower floor from one to two flats |
| | O.K. A.W. Campbell |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | COMPLETE AND O. K. INSPECTOR |