

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. 4-7717	LOCATION 1019 - 2nd Street
DATE 1/17/38	PURPOSE Gen. Repairs & remodeling of stone bldg.
ZONE	OWNER J. R. [unclear]
	ARCH'T. [unclear]
	CONTR. Chas. [unclear]

VAL. 3000 ⁰⁰	STORIES	ROOMS	APTS.	SIZE
-------------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
2/2/38	2 ND Insp Frame for Remodeling front & Interior of old "Saddle Rock" Restaurant
	O.K. A.H. Campbell
	4 TH Insp Remodeling Complete O.K. A.H. Campbell
3/24/38	COMPLETE AND O. K. <i>A.H. Campbell</i> INSPECTOR

REPRODUCED FROM THE ORIGINAL RECORDS OF THE NEW YORK STATE ARCHIVES