

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-9509</i>	LOCATION <i>1288 - Marian Way</i>			
DATE <i>11/5/41</i>	PURPOSE <i>Erect new dwlg.</i>			
ZONE	OWNER <i>Joe Neviss &</i>			
	ARCH'T.			
	CONTR. <i>M. Turtado.</i>			
VAL. <i>6000⁰⁰</i>	STORIES <i>—</i>	ROOMS <i>6</i>	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS	<i>Area</i>	
VENT SHAFTS		BOILER ROOMS	<i>1450⁰⁰</i>	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	<i>@ 3500</i>	
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK—REMARKS
2/28/42	1 ST /NSP. Forms in place ^{OK} A.W. Campbell
4/3/42	2 ND /NSP. Frame ^{OK} A.W. Campbell
4/20/42	3 RD /NSP. INT LATR ^{OK} A.W. Campbell
6/30/42	4 TH /NSP. Dwg with Attached Garage complete
6/30/42	<p>COMPLETE AND O. K. <i>Willie W. Campbell</i></p> <p style="text-align: right;">INSPECTOR</p>