

**BUILDING DIVISION - BUILDING INSPECTOR'S REPORT CARD**

**TYPE BUILDINGS**

<b>PERMIT NO.</b> 9553 <b>DATE</b> 6/8/32 <b>ZONE</b> Multi	<b>LOCATION</b> 1906 P. ST	
	<b>PURPOSE</b> Endn Rep + Alterations	<b>PHONES</b>
	<b>OWNER</b> Mrs L Gilpi	
	<b>ARCH'T</b>	
	<b>CONT-R</b> Owner	

<b>VAL.</b> 300	<b>STORIES</b> 2	<b>ROOMS</b>	<b>APTS.</b>	<b>SIZE</b>
--------------------	---------------------	--------------	--------------	-------------

<b>Light Shafts</b>		<b>Elevator Shafts</b>	
<b>Vent Shafts</b>		<b>Boiler Rooms</b>	
<b>Owner's Inspector</b>		<b>Sprinkler System</b>	
<b>Lath</b>		<b>Gas Vents</b>	
<b>Fire Escapes</b>		<b>Chimneys</b>	
<b>Stand Pipes</b>		<b>Skylights</b>	

DATE	CONDITION OF WORK—REMARKS
6/9/32	1 <sup>ST</sup> /NSP. Brick Foundation. <sup>OK</sup> A W Campbell
6/22/32	2 <sup>ND</sup> /NSP. Frame for Addition <sup>OK</sup> A W Campbell
6/2	3 <sup>RD</sup> /NSP. IN T & B O T L A O K <sup>OK</sup> A W Campbell
7/27/32	4 <sup>TH</sup> /NSP. Alterations Addition. Pri Garage and Repair to Dwg. A W Campbell
7/27/32	COMPLETE AND O. K. Alden H Campbell INSPECTOR