

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

**TYPE BUILDINGS**

<b>PERMIT NO.</b> B-12487 <b>DATE</b> 7/13/44. <b>ZONE</b>	<b>LOCATION</b> 1621 - R St.
	<b>PURPOSE</b> Rebuild parsonage of First Roman
	<b>OWNER</b> Christ Temple Church.
	<b>ARCH'T.</b>
<b>CONTR.</b> Quisenberry	

<b>VAL.</b> 400 <sup>00</sup>	<b>STORIES</b>	<b>ROOMS</b>	<b>APTS.</b>	<b>SIZE</b>
-------------------------------	----------------	--------------	--------------	-------------

<b>LIGHT SHAFTS</b>		<b>ELEVATOR SHAFTS</b>	
<b>VENT SHAFTS</b>		<b>BOILER ROOMS</b>	
<b>OWNER'S INSPECTOR</b>		<b>SPRINKLER SYSTEM</b>	
<b>LATH</b>		<b>GAS VENTS</b>	
<b>FIRE ESCAPES</b>		<b>CHIMNEYS</b>	
<b>STAND PIPES</b>		<b>SKYLIGHTS</b>	

DATE	CONDITION OF WORK—REMARKS
8/11/44	1 <sup>ST</sup> Insp. Forms for Rebuilding Parsonage of Church using sound old materials <sup>OK</sup> A W Campbell
	COMPLETE AND O. K. <span style="float: right;">INSPECTOR</span>