

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>H-1428</i>	LOCATION <i>5340 - S. Street</i>			
DATE <i>2/27/34</i>	PURPOSE <i>Repairs to Fire Loss (dwelling)</i>	PHONES		
ZONE <i>2-Fam</i>	OWNER <i>Martini (W & R Realty Co.)</i>	ARCH'T <i>Frank Maloney</i>		
VAL. <i>18600</i>	STORIES	ROOMS	APTS.	SIZE
Light Shafts		Elevator Shafts		
Vent Shafts		Boiler Rooms		
Owner's Inspector		Sprinkler System		
Lath		Gas Vents		
Fire Escapes		Chimneys		
Stand Pipes		Skylights		

DATE	CONDITION OF WORK-REMARKS
2/28/32	Made inspection of R. house to rid of
	ruin. Damaged by fire. All business
	materials removed with guns and put
	back in good shape. Completion OK
	R. Campbell
2/28/32	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. <i>William H. ...</i> INSPECTOR </div>