



PERMIT NO.

4711911R

CITY OF SACRAMENTO  
1231 I ST. ROOM 200  
BUILDING INSPECTIONS DIVISION

AREA NO.

3-R

WHEN CORRECTIONS HAVE BEEN MADE, CALL **264-5191** FOR REINSPECTION OF WORK.

JOB LOCATION

7485 MAPLE TREE

INSPECTION REQUESTED

Reeroof

THE UNDERSIGNED  BUILDING  PLUMBING  MECHANICAL  ELECTRICAL  
INSPECTOR THIS DAY INSPECTED THIS STRUCTURE FOR THE REQUESTED INSPECTION AND FOUND THE  
FOLLOWING VIOLATIONS OF CITY AND/OR STATE LAWS GOVERNING SAME:

**F** 04475

METAL FLASHING ON BACK SIDE  
OF GARAGE TO BE INSTALLED  
WITH SLOPE FOR DRAINAGE

INSPECTOR

DATE

10/8/97

BUILDING INSPECTIONS 264 5191

INSPECTOR'S COPY