

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-4274</i>	LOCATION <i>982 - Parkview Way</i>
DATE <i>11/16/39</i>	PURPOSE <i>Expect new dwlg - garl</i>
ZONE <i>2-2am</i>	OWNER <i>Wright Henderson</i>
	ARCH'T.
	CONTR. <i>Owner</i>

VAL. <i>4000</i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS.	SIZE
---------------------	---------------------	-------------------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	<i>Area</i>
VENT SHAFTS		BOILER ROOMS	<i>1000⁰</i>
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE.	CONDITION OF WORK-REMARKS
11/ /39	1 ST INSPECTION. Frames in place OR A.W. Campbell
12/26/59	2 ND INSPECTION. Frame OR A.W. Campbell
	<p data-bbox="305 911 454 955">COMPLETE AND O. K.</p> <p data-bbox="1263 928 1412 955">INSPECTOR</p>