

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE VII BUILDINGS

PERMIT NO. <i>5490</i>	LOCATION <i>2870 P St</i>		
DATE <i>11/4-9</i>	PURPOSE <i>Im Rep + Replumbing</i>	ROOMS	APTS.
ZONE	OWNER <i>M Anticevich</i>	PHONE	
	ARCH'T		
	CONT'R <i>Owner</i>		
	VAL. <i>500-</i>	STORIES	SIZE

FOUNDATION	STORY	BSMT	1	2	3	ROOF		
EX WALL	Joists						Chimneys	Cement Tests
	Beams and Girders						Fire Place	
Int Wall	Studs and Columns						Gas Water Heater	
	Bridging Fire Stops						Heater Closet	
Piers	Fire Escape Stand Pipes						Furnace	Window Courts
	Metal Lath						Boiler Room	
	Stairs						Elevator Shaft	

DATE	CONDITION OF WORK—REMARKS
11/12/29	<p>Inspected repairs being made to work - New Composition Shingle Roof - New Galv Iron Gutters. Removing old interior plastering and replastering over 20 gauge lath. Plastering over old lath, also remodeling rear porch + steps. Owner will get permit today. <i>W. Campbell</i></p>
11/27/29	<p>300 / N.S.P. / INT. LATH ^{Old lath removed, replaced with 20 gauge} <i>Plastering over old lath, also remodeling rear porch + steps. <i>W. Campbell</i></i></p>

COMPLETED
AND O.K.

INSPECTOR