

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B 6949</i>	LOCATION <i>6343 - 2<sup>nd</sup> Ave</i>
DATE <i>11/8/40</i>	PURPOSE <i>New duplex</i>
ZONE <i>-</i>	OWNER <i>E. L. Hecker</i>
	ARCH'T. <i>J. G. Hecker</i>
	CONT'R. <i>J. G. Hecker</i>

VAL. <i>2450<sup>00</sup></i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS.	SIZE
-------------------------------	---------------------	-------------------	-------	------

LIGHT SHAFTS	ELEVATOR SHAFTS	<i>area 1750<sup>00</sup> @ 30%</i>
VENT SHAFTS	BOILER ROOMS	
OWNER'S INSPECTOR	SPRINKLER SYSTEM	
LATH	GAS VENTS	
FIRE ESCAPES	CHIMNEYS	
STAND PIPES	SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
11-13	15' Ins of Formwork OK <i>Quartz</i>
12-0	2 " Formwork " <i>Quartz</i>
	<div style="display: flex; justify-content: space-between;"> <span data-bbox="309 945 460 991"><b>COMPLETE AND O. K.</b></span> <span data-bbox="1303 962 1463 988"><b>INSPECTOR</b></span> </div>