

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-11050</i>	LOCATION <i>1128 - 2nd Street -</i>			
DATE <i>1/26/43</i>	PURPOSE <i>General repairs to Bldg -</i>			
ZONE <i>Com.</i>	OWNER <i>F</i>			
	ARCH'T.			
	CONTR. <i>N.G. Henchen</i>			
VAL. <i>300⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

117
118
119
120
121
122
123
124
125
126
127
128
129
130
131
132
133
134
135
136
137
138
139
140
141
142
143
144
145
146
147
148
149
150
151
152
153
154
155
156
157
158
159
160
161
162
163
164
165
166
167
168
169
170
171
172
173
174
175
176
177
178
179
180
181
182
183
184
185
186
187
188
189
190
191
192
193
194
195
196
197
198
199
200

DATE	CONDITION OF WORK-REMARKS
2/2/42	General Repairs to interior of Store including new stairway in rear to yard completed
2/2/43	COMPLETE AND O. K. <i>Alfred W. Campbell</i> INSPECTOR