

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

R10-F342

TYPE BUILDINGS

M-22-7.

PERMIT NO.

LOCATION

3417 - 2nd ave.

DATE

PURPOSE

Erect public repair garage

OWNER

Stenkawa

ZONE

ARCH'T.

CONT'R.

Robt. L. Morris

VAL.

\$ 3600

STORIES

ROOMS

APTS.

SIZE

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
2/21/50	Forms Insp. <i>P. E. Buckius</i>
3/2/50	Top. Road Beam <i>" " "</i>
3/4/50	Lower Road Beam <i>P. E. Buckius</i>
	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. INSPECTOR </div>