

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-24770</i>	LOCATION <i>915 1/2 - 3rd street.</i>
DATE <i>3-16-49</i>	PURPOSE <i>Repair - plug</i>
ZONE	OWNER <i>C. Wong</i>
	ARCHT.
	CONTR. <i>Chas. V. ...</i>

VAL <i>\$800</i>	STORIES	ROOMS	APTS.	SIZE
------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
3/25/49	Frame Insp. on added Partitions (So. Side / stairs) and Wiring up Ceiling
	A. E. Buckner
	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. INSPECTOR </div>