

## BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>B-34272</i>	LOCATION <i>111 1/2 - 5th Street</i>
DATE <i>Jan. 8-55</i>	PURPOSE <i>Remodel store front.</i>
ZONE	OWNER <i>F. Hernandez</i>
	ARCHT. <i>[Signature]</i>
	CONTR. <i>Harry Hernandez</i>

VAL <i>150<sup>00</sup></i>	STORIES <i>1</i>	ROOMS <i>1</i>	APTS.	SIZE
-----------------------------	------------------	----------------	-------	------

LIGHT SHAFTS	<div style="border: 1px solid black; border-radius: 50%; padding: 20px; display: inline-block;"> <i>wrecked</i>  <i>11</i> </div>	ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE

CONDITION OF WORK—REMARKS

4/28/52

Final Insp.

Q. E. Buckius

COMPLETE  
AND O. K.

INSPECTOR