

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-20926</i>	LOCATION <i>2609 — 5th St.</i>			
DATE <i>12/20/47</i>	PURPOSE <i>Repair Shop Bldg. - grease catch</i>			
ZONE	OWNER <i>Sam Yerga</i>			
	ARCH'T.			
	CONTR. <i>Owner</i>			
VAL. <i>1000</i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS			ELEVATOR SHAFTS	
VENT SHAFTS			BOILER ROOMS	
OWNER'S INSPECTOR			SPRINKLER SYSTEM	
LATH			GAS VENTS	
FIRE ESCAPES			CHIMNEYS	
STAND PIPES			SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
4/7/48	FORMS INSP. <i>R. E. Jones</i>
1/20/48	FRAME " " "
	<p data-bbox="259 816 380 854">COMPLETE AND O. K.</p> <p data-bbox="1064 829 1191 847">INSPECTOR</p>

