

**BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD**

**TYPE BUILDINGS**

PERMIT NO. <i>No Over</i> <i>(Re Roof Rep)</i>	LOCATION 2912 P. St.
DATE July 28. 1931	PURPOSE Re-Roof Part of Roof of Dwlg - Composition Shingles
ZONE Multiple Family	OWNER L. M. TSOLO
	ARCH'T
	CONT-R Owner

VAL.	60 <sup>00</sup>	STORIES	1	ROOMS		APTS.		SIZE
------	------------------	---------	---	-------	--	-------	--	------

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
7/28/31	<p>Issued this No Charge Permit for Re-Roofing  part of Roof of Dwell. with Composition Shingles  OK A.W. Campbell</p>
	<p><i>(This section is crossed out with a diagonal line)</i></p>
7/29/31	<p>COMPLETE AND O.K. <i>Allen W Campbell</i> INSPECTOR</p>