

R 300 F 597-598

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$10.00

TYPE BUILDINGS

| | | | | | |
|-------------------------|--------------------------|------------------------------------|------------------------|----------------------|-------------|
| PERMIT NO. | | | | | |
| S-6896 | LOCATION | 2414 - 16th Street | | | A-2 |
| DATE | PURPOSE | Construct Sign | | | |
| Apr-19-71 | OWNER | 7-Up Company | Same | | |
| ZONE | ARCH'T | | | | |
| | CONTR | Best Neon 3508 - W. Capitol Avenue | | | |
| VAL. \$900. | | STORIES | ROOMS | APTS. | SIZE |
| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | PHONE (O) (C) | |
| | | | | 371 3633 | |
| FORM | | | | | |
| JOIST | | | | | |
| FRAME SHEET ROCK | | | | | |
| FINAL | <i>M-1-73 Mentor</i> | | | | |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|------|---|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | <p data-bbox="283 871 412 923">COMPLETE AND OK</p> <p data-bbox="1151 897 1290 923">INSPECTOR</p> |