

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-8975</i>	LOCATION <i>624 - Swanston Dr.</i>
DATE <i>8/25/41</i>	PURPOSE <i>Erect new dwlg. &amp; ja.</i>
ZONE <i>2 - Fam.</i>	OWNER <i>H. Sieden.</i>
	ARCH'T. <i>P. A. Schuler</i>
VAL. <i>4200</i>	CONTR. <i>P. A. Schuler</i>
	STORIES
	ROOMS
	APTS.
	SIZE

LIGHT SHAFTS	ELEVATOR SHAFTS
VENT SHAFTS	BOILER ROOMS <i>Area</i>
OWNER'S INSPECTOR	SPRINKLER SYSTEM <i>1168'</i>
LATH	GAS VENTS <i>@ 35'</i>
FIRE ESCAPES	CHIMNEYS
STAND PIPES	SKYLIGHTS

DATE	CONDITION OF WORK-REMARKS
9/2/41	1 <sup>ST</sup> INSP FORMS IN PLACE <sup>OR</sup> A.W. Campbell
9/30/41	2 <sup>ND</sup> INSP. FRAME <sup>OR</sup> A.W. Campbell
10/15/41	3 <sup>RD</sup> INSP. INT & EXT BATH <sup>OR</sup> A.W. Campbell
	<div style="display: flex; justify-content: space-between;"> <span data-bbox="284 844 411 885">COMPLETE AND O. K.</span> <span data-bbox="1121 865 1257 885">INSPECTOR</span> </div>