

912 4354-357

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$73.00

Ptn. *lying*
 North of Lot 17
 Riverside Village. TYPE BUILDINGS

PERMIT NO. **E-2823** LOCATION *1021* ~~1115~~ - Piedmont Drive A-3

DATE **Dec. 5-62** PURPOSE **Const. dwelling & attached garage.**
 OWNER **Donald Cooley 4800 - Franklin Blvd.**

ZONE **R-1** ARCH'T **Owner** CONTR **Same 451-0462**

VAL. \$21,200.	STORIES 1	ROOMS 6	APTS.	624-sq. ft. SIZE 2,190 sq. ft.
-----------------------	---------------------	-------------------	-------	-----------------------------------

INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP
-------	------	------------	-----------------

FORM	12-19-62	[Signature]	<h1 style="font-size: 4em; margin: 0;">VARIANCE</h1>
JOIST	12-31-62	[Signature]	
FRAME	3-8-63	[Signature]	
SHEET ROCK			
FINAL	6-3-63	[Signature]	

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
12/27/62	Checked Form for det. garage. Form OK.
12/31/62	Pl. 18 out traps & lapped in furnace furnace room. Also equipped with factory. Exhaustion must be done not returned to work
1-11-63	Checkers checked furnace puller
3-5-63	Pl. 2x8 ceiling joint must be blocked Puller
COMPLETE AND OK	INSPECTOR