

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE VII BUILDINGS

| | | | |
|----------------------------------|--|----------------|--------------|
| PERMIT NO. <i>5607</i> | LOCATION <i>2209 Portola</i> | | |
| DATE <i>11/23/49</i> | PURPOSE <i>For Parking</i> | ROOMS | APTS. |
| ZONE | OWNER <i>H R Gungor</i> | PHONE | |
| | ARCH'T | | |
| | CONT'R <i>Owner</i> | | |
| | VAL. <i>100 -</i> | STORIES | SIZE |

| FOUNDATION | STORY | BSMT | 1 | 2 | 3 | ROOF | | |
|-----------------|--------------------------------|------|---|---|---|------|-------------------------|----------------------|
| EX WALL | Joists | | | | | | Chimneys | Cement Tests |
| | Beams and Girders | | | | | | Fire Place | |
| Int Wall | Studs and Columns | | | | | | Gas Water Heater | |
| | Bridging Fire Stops | | | | | | Heater Closet | |
| Piers | Fire Escape Stand Pipes | | | | | | Furnace | Window Courts |
| | Metal Lath | | | | | | Boiler Room | |
| | Stairs | | | | | | Elevator Shaft | |

| DATE | CONDITION OF WORK—REMARKS |
|----------|---------------------------------------|
| 11/27/29 | 1 Dump Frame Garage OK R.H. Reuter |
| 12/9/29 | 2 Dump Ferried & OK R.H. Reuter |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

COMPLETED
AND O.K.

R.H. Reuter

INSPECTOR