

231 F 96. - 101

Lot $W\frac{1}{2}$		BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD		\$156.50	
Lot 3		TYPE BUILDINGS			
Block 25-26 P-Q					
PERMIT NO.	LOCATION				A-2
F-9237	2518 - P Street				
DATE	PURPOSE	Const. 7 unit apartment house			
12-26-67	OWNER	Robert R. Gallaway 819 - J Street			
ZONE	ARCH'T	R. Wm. Isaacson 2550 Valley Road			
R-5	CONTR	Owner same			
VAL. \$57,400.	STORIES	ROOMS	APTS.	3325 2nd floor	
	2			3325 sq. ft.	
INSP.	DATE	BLDG. TYPE V No.	Hr.	OCCUPANCY GROUP H-1	PHONE (O) (C)
FORM	12-29-67	Numerous			
JOIST					
FRAME	3-39-68	Numerous			
SHEET ROCK	4-8-68	Numerous			
FINAL	5-22-68	C. Hammer			
					Ent.

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
1-17-68	RT-Beam & slab - No clearance given
1-18-68	OK slab
1-25-68	Checked wall with required. Blocked not ready
1-26-68	OK 16' x 30' BB
1-30-68	RT-Barricade not up
2-6-68	OK jump case quantity
2-5-68	RT-Beam - Not ready
	COMPLETE AND OK
	INSPECTOR

Baskets

Hammer

Hammer

Hammer

Hammer

Hammer

Hammer

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$156.50

TYPE BUILDINGS

Card #2

PERMIT NO. F-9237		LOCATION 2518 - P Street A-2			
DATE 12-26-67		PURPOSE Const. 7-unit apartment house			
ZONE R-5		OWNER Robert R. Gallaway 819 - J Street			
		ARCH'T R. Wm. Isaacson 2550-Valley Road			
		CONT'R Owner Same			
VAL \$57,400.		STORIES 2	ROOMS	APTS.	3,325 2nd fl size 3,325 sq. ft.
INSP.	DATE	BLDG. TYPE V no hr.		OCCUPANCY GROUP H-1	PHONE (O) (C)
FORM					
JOIST					
FRAME					
SHEET ROCK					
FINAL					

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
3-13-67	P4 Dry nail - no nailed correctly <i>Hammers</i>
3-14-67	P4 Dry nail <i>Hammers</i>
4-5-68	P4 - not ready <i>Hammers</i>
5-23-68	P7 Final - Kitchen exhaust ducts not 1" clear cut too close to medallion <i>Hammers</i>
	<p data-bbox="315 1036 467 1103">COMPLETE AND OK</p> <p data-bbox="1323 1066 1480 1097">INSPECTOR</p>