

**BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD**

**TYPE BUILDINGS**

<b>PERMIT NO.</b> 8246	<b>LOCATION</b> 52 Maple Park	<b>PHONES</b> 1709-4 Ann
<b>DATE</b> 7/13	<b>PURPOSE</b> Fr Rev V. 1976	<b>OWNER</b> [Signature]
<b>ZONE</b> 2-1	<b>CONT-R</b> [Signature]	

<b>VAL.</b> 5500	<b>STORIES</b> 1	<b>ROOMS</b> 6	<b>APTS.</b> 1	<b>SIZE</b> [Handwritten]
---------------------	---------------------	-------------------	-------------------	------------------------------

<b>Light Shafts</b>		<b>Elevator Shafts</b>	
<b>Vent Shafts</b>		<b>Boiler Rooms</b>	
<b>Owner's Inspector</b>		<b>Sprinkler System</b>	
<b>Lath</b>		<b>Gas Vents</b>	
<b>Fire Escapes</b>		<b>Chimneys</b>	
<b>Stand Pipes</b>		<b>Skylights</b>	

DATE	CONDITION OF WORK-REMARKS
7/9-31	1 <sup>st</sup> Insp Forms ok P.H. Punter
8/10-31	2 " Frame " P.H. Punter
8/21-31	3 " Int Suth " P.H. Punter
9/28-31	4 " Finald ok Certificate of occupancy issued.
	A.C. up
	<div style="display: flex; justify-content: space-between;"> <span data-bbox="336 970 520 1027">COMPLETE AND O.K.</span> <span data-bbox="588 906 1192 1056" style="font-size: 2em; font-family: cursive;">P.H. Punter</span> <span data-bbox="1260 998 1444 1027">INSPECTOR</span> </div>