

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

| | |
|------------------------------|----------------------------------|
| PERMIT NO. <i>A-6963-</i> | LOCATION <i>229-905</i> |
| DATE <i>9/16/37.</i> | PURPOSE <i>Resingle dwlg.</i> |
| ZONE | OWNER <i>John H. Ferry.</i> |
| | ARCH'T. |
| | CONT'R. <i>Walsh Roofing Co.</i> |

| | | | | |
|------------------------------|---------|-------|-------|------|
| VAL. <i>116⁰⁰</i> | STORIES | ROOMS | APTS. | SIZE |
|------------------------------|---------|-------|-------|------|

| | |
|-------------------|------------------|
| LIGHT SHAFTS | ELEVATOR SHAFTS |
| VENT SHAFTS | BOILER ROOMS |
| OWNER'S INSPECTOR | SPRINKLER SYSTEM |
| LATH | GAS VENTS |
| FIRE ESCAPES | CHIMNEYS |
| STAND PIPES | SKYLIGHTS |

| DATE | CONDITION OF WORK—REMARKS |
|-------------|----------------------------------|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | COMPLETE AND O. K. |
| | INSPECTOR |